

SRS by TRW SAK-TC234L-32F200F

NXWI5E006E

Air Bag Sensor
TOYOTA
89170-0C572
335384-107
12V

90

UART

RXD
118

PDX
121

TXD
119

Log0
143


Log0
144

VCC
3.75

GND

RST
97

<http://pavelpervomaysk.com>



CAN
L

CAN
H

+12

-12

Tested:

- 89170-02N50 Corolla
- 89170-02N80 Corolla
- 89170-02P10
- 89170-02R60
- 89170-02T00
- 89170-02T10
- 89170-07390 Avalon
- 89170-07391
- 89170-07400
- 89170-07401
- 89170-07480 Avalon
- 89170-0C570
- 89170-0C572
- 89170-0C573
- 89170-0C581
- 89170-0C582 Tundra
- 89170-0C583 Tundra
- 89170-0C590
- 89170-0C592 Highlander
- 89170-0C593
- 89170-0C630 Tundra