


VAG VW30 / VW31 / VW32



<http://loavelpervomaysk.com.ua>

VCDS Release 21.3.0: 15-Airbags, Open Controller

Comm Status: Latency=3 ms, Protocol: UDS

Controller Info:

VAG Number:	4N0 959 655 AJ	Component:	AirbagVW31 H19 2730
Soft. Coding:	Long Coding	Shop #:	Imp: 028 WSC 31414
Extra:			
Extra:	Geraet 00001		

<https://youtu.be/WhrEgQeN4nE>

VCDS Release 21.3.0: 15-Airbags, Advanced Measuring Values

Sample Rate: 1.1

VCDS Advanced Measuring Values

Group UDS requests

Loc.	Description	Actual
IDE01271	Number of rollover bar deployments	0
IDE01555	Number of frontal crashes	1
IDE01556	Number of side crashes driver side	0
IDE01557	Number of side crashes frt.pass. side	0
IDE01558	Number of rear crashes	0
IDE01559	Number of rollover crashes	1
IDE01560	Number of activations of active head restraint	0
IDE02246	Number of activations of pedestrian protecti...	0

1

VCDS Release 21.3.0: 15-Airbags, Advanced Measuring Values

Sample Rate: 1.1

VCDS Advanced Measuring Values

Group UDS requests

Loc.	Description	Actual
IDE01271	Number of rollover bar deployments	0
IDE01555	Number of frontal crashes	0
IDE01556	Number of side crashes driver side	0
IDE01557	Number of side crashes frt.pass. side	0
IDE01558	Number of rear crashes	0
IDE01559	Number of rollover crashes	0
IDE01560	Number of activations of active head restraint	0
IDE02246	Number of activations of pedestrian protecti...	0

2

VCDS Release 21.3.0: 15-Airbags, Fault Codes

VCDS Fault Codes

Use Aggressive Mode
 Display Freeze Frame Data

Controller Info:

VAG Number: 4N0 959 655 AJ Component: AirbagVW31 H19 2730

Fault Codes:

Fault Codes have been Erased

2 Faults Found:

12615936 - FlexRay Databus
U0081 00 [008] - No Communications [FlexRay Channel A no communication]
Intermittent - Confirmed - Tested Since Memory Clear

9682162 - Multiple collision brake
B13BC F2 [137] - No function
MIL ON - Confirmed - Tested Since Memory Clear

3